

Tuesday, 28 January 2025

UPDATE: Flight disruptions at George Airport

Air Traffic and Navigation Services (ATNS) SOC Ltd would like to provide an update regarding the flight disruptions that began yesterday at George Airport due to severe inclement weather conditions.

The airport is still affected by a low cloud base and strong surface winds that make landing on Runway 29 not feasible. Aircraft are therefore forced to operate on Runway 11, whose instrument landing system (ILS) flight procedure is still under maintenance. As a result, some flights are forced to divert as a safety precaution.

ATNS will continue to monitor the situation and advise airlines and aviation stakeholders accordingly. Ends//

Issued by the Air Traffic and Navigation Services (ATNS) SOC Ltd

Mphilo K. Dlamini – Head of Corporate Affairs and Communications

076 639 5800

mphilod@atns.co.za